



When your electronic or electrical equipment gets wet this season, use the CRC 5-step approach



- 1** Switch off and disengage equipment
- 2** Clean off oil and dirt with QD contact cleaner (Code 32429) – apply liberally!!
- 3** Displace moisture and water using 2-26 (Code 92005) – apply liberally!!!
- 4** Clean off again with QD contact cleaner (Code 32429) – apply liberally!!
- 5** Take Megga readings after equipment has been cleaned. If readings are not up to minimum resistance levels, REPEAT application

DISPLACE MOISTURE EFFECTIVELY